


C.S. OF



Crack penetrating full depth of slab and water seeps and drops on the occupants

We missed the 0.3 l extension of the slab and the owner after consulting other consultant blames this is the reason for crack in slab

LAYOUT OF ROOF SLAB & BEAMS OVER GROUND FLOOR

(ALL GRID DIMENSIONS SHALL BE CHECKED WITH ARCHITECTURAL DRG.)